

ERRATUM - Tarif Margot 2024 - FR

Page 64. M02, M03, M04, M05 THÉTIS.

Suppression de la REF. 4102

Page 95. M20, M21, M22, M23 CIRCÉ.

Suppression de la REF. 4102

Page 176. M13, M14 ORSAY.

REF. 2308T1 : erreurs de prix : **A** : 2 842 **B** : 3 553 **C** : 3 695 **D** : 3980 **E** : 5 969

Page 404. MS03 VICTORIAN.

REF. 8R300 : Disponible uniquement en finitions A1 & D1.

Pages 428-429. MS05 EDWARD.

REF. MS00-8C251 : erreur de visuel et de schéma, se reporter au site internet

REF. MS00-8C246 : erreur de visuel et de schéma, se reporter au site internet

ERRATUM - Margot 2024 Pricelist - ENG

Page 64. M02, M03, M04, M05 THÉTIS.

Suppression of REF. 4102

Page 95. M20, M21, M22, M23 CIRCÉ.

Suppression of REF. 4102

Pages 428-429. MS05 EDWARD.

REF. MS00-8C251: photo and drawing error, please report to the website

REF. MS00-8C246: photo and drawing error, please report to the website

Page 404. MS03 VICTORIAN.

REF. 8R300: Available only in A1 & D1 finishes.

Page 176. M13, M14 ORSAY.

REF. 2308T1: pricing error: **A**: 2 842 **B**: 3 553 **C**: 3 695 **D**: 3980 **E**: 5 969