

ERRATUM - Tarif Margot 2025 - FR

Page 95. M20, M21, M22, M23 CIRCÉ.

REF. 3311T : erreur de prix : **A** : 3 076 ; **B** : 3 845 ; **C** : 3 999 ; **D** : 5 537 ; **E** : 6 460

Page 136. M38, M39 WESTMINSTER.

Erreur de légende sur la photo en haut à gauche : Ref. M38-C16-1302

Page 168. M13, M14 ORSAY.

Erreur de légende sur les photos en haut : Ref. M13-C16-2201T et Ref. M13-C16-1302

Page 408. MS03 VICTORIAN.

REF. MS03-8R300 : Référence disponible en finitions A1 & D1 - Prix pour le D1 : 530

Pages 428-429. MS05 EDWARD.

REF. MS00-8C251 : erreur de visuel et de schéma, se reporter au site internet

REF. MS00-8C246 : erreur de visuel et de schéma, se reporter au site internet

ERRATUM - Margot 2025 Pricelist - ENG

Page 95. M20, M21, M22, M23 CIRCÉ.

REF. 3311T: pricing error: **A**: 3 076 ; **B**: 3 845 ; **C**: 3 999 ; **D**: 5 537 ; **E**: 6 460

Page 136. MS38, M39 WESTMINSTER.

Caption error on the top left photo: Ref. M38-C16-1302

Page 168. M13, M14 ORSAY.

Caption error on the top photos: Ref. M13-C16-2201T and Ref. M13-C16-1302

Page 408. MS03 VICTORIAN.

REF. MS03-8R300: Reference available in A1 & D1 finishes - Price for D1: 530

Pages 428-429. MS05 EDWARD.

REF. MS00-8C251: photo and drawing error, please refer to the website

REF. MS00-8C246: photo and drawing error, please refer to the website